



Code N.

697095

Date

03.10.2007

BV n°

ART.9.2007.183

CERTIFICAT D'INSPECTION
INSPECTION CERTIFICATE**BUREAU**
VERITAS**INSPECTION CERTIFICATE**

Inspection ordered by: ENVIRONMENTAL PACKAGING TECHNOLOGIES–ARGENTINA Branch.
Person in charge: Vicente Molina – Country Manager.

Inspection place: Uspallata 1988 Dorrego – Guaymallen - Mendoza
ALL Base Retiro - Buenos Aires

Inspection date: Round Trip 1: August 24 -27 and September 3-7-8, 2007
Round Trip 2: September 7-8-17 and 22, 2007

Service: Mechanic Resistance Test of a Flexi-tank.

Product: Flexi-tank N° 061228025B

Mark: Big Red

Inspection

We, Bureau Veritas, hereby certify that upon request of Vicente Luis Molina , have conducted an inspection of a Flexi-tank, and report our finding as follows:

Inspection result

In accordance with instructions, Bureau Veritas representative was present at the mentioned inspection sites to perform a visual Mechanic Resistance Test of a Flexi-tank loaded with water.

A visual inspection was conducted to verify the good condition of the container, after that, Bureau Veritas inspected the correct storage of the Flexi-tank into one twenty feet container.

Once the Flexi-tank N° 061228025B was loaded into the Container, we witnessed loading of 24.000 litres of water into the flexi tank.

After the Flexi tank was loaded , it was duly sealed with BV metal seal number: 247301.

Round trip 1:

Container Nr.	Inspection site	Flexitank Condition	BV Seal Nr.
TRLU291336-7	Mendoza	Good without filtration	247302
TRLU291336-7	Buenos Aires	Good without filtration	246424
TRLU291336-7	Mendoza	Good without filtration	247309

Round trip 2:

Container Nr.	Inspection site	Flexitank Condition	BV Seal Nr.
TRLU291336-7	Mendoza	Good without filtration	247309
TRLU291336-7	Buenos Aires	Good without filtration	A090286
TRLU291336-7	Mendoza	Good without filtration	247312

Distance between Mendoza – Buenos Aires: about 1.049 kilometres. Total trip about 4.196 kilometres

At the end of the last trip we noted a small waste in the right lower corner, some liquid in the container at the lower right and the right side of the flexi-tank a light spot. At the top of the flexi-tank we also noted a little filtration.

This inspection was found to be Satisfactory.

Cette inspection a été effectuée dans le cadre des conditions générales du Bureau Veritas (voir au dos), elle ne dégage pas le vendeur de ses obligations contractuelles envers l'acheteur.

This inspection has been carried out within the scope of Bureau Veritas General Conditions (see over leaf), it does not release the seller from his contractual obligations towards the buyer.



A set of photographs is attached.

This inspection has been carried out within the scope of Bureau Veritas General Conditions, and the certificate issued does not release manufacturers, suppliers, buyers and other parties involved in the transaction, from their contractual obligations and responsibilities.

District Argentina, Buenos Aires, October 3rd 2007.

